



IXYS Colorado/Directed Energy, Inc.  
1609 Oak Ridge Drive Suite 100  
Fort Collins, CO 80525  
Phone: 970-493-1901  
[www.ixyscolorado.com](http://www.ixyscolorado.com)

## Product Discontinuation Notice

**Date:** February 1, 2017

**Part Number:** PCO-7120 50A Laser Diode Driver

IXYS Colorado/Directed Energy, Inc. is committed to providing innovative and reliable products, and supporting them as long as possible. However, it occasionally becomes necessary to discontinue a product and offer an upgraded replacement.

**Last Order Date:** Orders for the PCO-7120 50 Amp Laser Diode Driver will be accepted until stock on hand is depleted, at which point the PCO-7120 will be discontinued and orders no longer accepted.

**End of Product Support:** IXYS Colorado will continue to offer support for this product, however it can no longer guarantee the availability of spare parts and repair services for the listed products. Note that some parts may continue to be available as long as supplies last.

## Recommended Replacement

**Replacement Part Number:** TBD

The replacement for the PCO-7120 is under development and will be available in the near future. Please contact the factory for specific details.

We will do all that we can to work with you so that your operations will not be hindered by this product change. Should you have any questions please contact Bob Schmid, IXYS Colorado/DEI sales and customer support, at 970-493-1901, email [b.schmid@ixyscolorado.com](mailto:b.schmid@ixyscolorado.com). We look forward to answering any questions you may have.